

Workshop Application Update

I am pleased to bring you news of the latest update to the Workshop Web Application.

The release deployed on the evening of 7th July included the following items:

Component search improvements – To assist users in locating the correct component on our interactive diagrams we have added a drop-down option to display the full list of available components. There is also now a 'clear search' function that allows users to clear the search bar with a single click.

Additional component images – We have added another 50 generic component images that will appear on interactive diagrams and component pages.

Translation update – The latest translation update has been completed to ensure that all the latest application text is displayed in the correct user language.

10,000 Colour diagrams - In addition to the application updates we have also recently added another 10,000 colour wiring diagrams covering 25,000 models.

Image quality upgrade – We have also updated all our service and component location illustrations to use higher resolution images giving users more detail and clarity to enjoy.

6 additional small bug fixes and enhancements – More bugs fixed to improve reliability and user experience.

Autodata updates dashboard

Autodata Component locations [Back to all technical information](#) **BMW 3 Series**

General components

Search components

- 3: AC/heater blower control module - behind glove box
- 15: Alarm system in car movement sensor 1 (E93)
- 16: Alarm system in car movement sensor 2 (E93)
- 13: Alarm system gradient sensor - in alarm system horn
- 14: Alarm system horn - behind LH rear wheel arch liner
- 19: Audio unit output amplifier - LH load area
- 20: Auxiliary heater control module - behind bumper
- 17: Alarm system in car movement sensor 3 - in door (E93)
- 18: Alarm system in car movement sensor 4 - in door (E93)
- 23: Convertible top open/close motor (incorporates relays) - under load area floor
- 24: Cruise control distance range control module - behind fascia
- 11: Airbag side assembly crash sensor (E92) - behind RH rear side

Print on component pages

Autodata Wiring diagram [Back to all technical information](#) **Audi A4**

All models, ABS
All models → 07/04

A236 Steering column function control module

B19, B20, B21, B22, A236, S212, S13

Full list of bug fixes & Minor enhancements

- If a vehicle has more than one serp illustration and you only open the Aux drive belt accordion, no drag bar appears
- In Russian, the text on the Chose data category page is breaking
- Estimate calculator - Parts printing - text cut off
- Mandrill email template bug
- No scroll bar when single image is open
- Address not shown correctly on Print Estimate

Thank you and well done to everyone involved. **Nick Capek**